

**Inspection Report**

Report No.: XYSK-140606  
Supplier : XY-GLOBAL

Inspection Date: 2<sup>th</sup> July, 2014  
Inspector: Leo

Inspection only for: PO . XYSK-140606 Item No. XY31SY006	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY006	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :													
													
1. Packing	2. Product												
													
3. Product	4 Product												
	<p><b>XY-GLOBAL</b> 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd</p> <table border="1"> <tr> <td>Inspection Report</td> <td>Product Type</td> <td>Inspection Date</td> </tr> <tr> <td>XY31SY006</td> <td>XY31SY006</td> <td>2014.07.02</td> </tr> <tr> <td>Inspector</td> <td>Inspector</td> <td>Inspector</td> </tr> <tr> <td>Leo</td> <td>Leo</td> <td>Leo</td> </tr> </table> <p>Inspection Result: PASS</p> <p>Inspection Summary: The inspection sample plan is 100% inspection.</p>	Inspection Report	Product Type	Inspection Date	XY31SY006	XY31SY006	2014.07.02	Inspector	Inspector	Inspector	Leo	Leo	Leo
Inspection Report	Product Type	Inspection Date											
XY31SY006	XY31SY006	2014.07.02											
Inspector	Inspector	Inspector											
Leo	Leo	Leo											
5. Product:	6. report												

