

□□□□□□□□□□

Inspection Report

Report No.: XYS-130318
 Supplier : XY-GLOBAL

Inspection Date: 20th Apr, 2013
 Inspector: Leo

Inspection only for: PO . XYS-130318 Item No.XY-120116	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-120116	5000PCS	10% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
材質	
公差	+/-0.01
表面処理	T / T 50
検査	
包装	
納期	
備考	
1.Name	ADC12 A380
2.Process	
3.	ADC12 A380
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11.	ISO 9001
1.	10 ISO
2.	
3.	kindls available
4.	
5.	
6.	
7.	
	NBSP;
	ISO9001
	OEM