

Inspection Report

Report No.: XYDA-140502
 Supplier : XY-GLOBAL

Inspection Date: 1th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYDA-140502 Item No.140589	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140589	14000PCS	1% inspection	0pcs	No failure	14000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Product
3. Product	4 Product
5. Product:	6. Product:

品名	汎用部品OEM部品
品番	ADC12A380
仕様	
用途	
材質	
加工	CNC加工
公差	gague
MOQ	
公差	+/-0.01
公差	T / T 50 / T ;
公差	
公差	
公差	
公差	T / T 50 20-25
公差	
1.Name汎用部品OEM部品	
2.Process	
3.汎用部品ADC12A380	
4.	
5.Tolerance +/-0.01	
6.Quality 100	
7.Specification OEM	
8. 25-30	
9. accessoried	
10. Austrial	
11. ISO 9001	
1. 10 ISO	
2.	
3. sureface kinds available	
4.	
5.	
6.	
7.	
ISO9001	
OEM	