

**Inspection Report**

Report No.: XYSL-150625  
 Supplier : XY-GLOBAL

Inspection Date: 28<sup>th</sup> July, 2015  
 Inspector: Leo

Inspection only for: PO . XYSL-150625 Item No. XY31XL023	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL023	10000PCS	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

物料	数控加工CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
公差	±0.01
表面处理	阳极氧化
包装	防静电袋
最小起订量	500件
交货期	3-5天
付款方式	预付50%尾款50%
质量保证	提供检测报告
运输方式	快递
交货地点	工厂或仓库
其他要求	按图加工
备注	
1. 数控加工CNC	
2. 材料AL6061 AL6065 AL6063 AL7075	
4. 公差±0.01	
5. 表面处理±0.01	
6. 包装100件	
7. 最小起订量500件	
8. 交货期25-30天	
9. 付款方式预付50%尾款50%	
10. 质量保证提供检测报告	
11. 运输方式ISO 9001	
其他要求	
1.10 数控加工ISO	
2. 材料AL6061 AL6065 AL6063 AL7075	
3. 公差±0.01	
4. 表面处理±0.01	
5. 包装100件	
6. 最小起订量500件	
7. 交货期25-30天	
8. 付款方式预付50%尾款50%	
9. 质量保证提供检测报告	
10. 运输方式ISO 9001	
11. 其他要求	
按图加工	
备注	
OEM	

Safety is our serious job for our worker and engineer team

