

**Inspection Report**

**Report No.:** XYI-140315  
**Supplier :** XY-GLOBAL

**Inspection Date:** 12<sup>th</sup> Apr, 2014  
**Inspector:** Leo

Inspection only for: PO . XYI-140315 Item No.142140	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142140	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

**Digital photo records :**

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	高精度デジタルゲージOEM部品
品番	ADC12-A380
仕様	
材質	ステンレス
加工	CNC加工
公差	±0.01mm
表面処理	鏡面研磨
検査	100%
納期	25-30日
付属品	accessories
規格	Austrian
認証	ISO 9001
備考	
1. Name	高精度デジタルゲージ
2. Process	CNC加工
	ADC12-A380
4. 公差	±0.01mm
5. Tolerance	±0.01mm
6. 検査	100%
7. Specification	serice
8. 納期	25-30日
9. 付属品	accessories
10. 規格	Austrian
11. 認証	ISO 9001
備考	
1. 10日以内	ISO
2. 検査	
3. 種類	kindls available
4. 公差	
5. 検査	
6. 納期	
7. 付属品	
備考	
	NBSP;
	ISO9001
	OEM