

□□□□□□□□LED□□

**Inspection Report**

**Report No.:** XYS-130705  
**Supplier :** XY-GLOBAL

**Inspection Date:** 10<sup>th</sup> Aug, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130705 Item No.XY-2531400	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-2531400	3000PCS	5% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

項目	項目名稱
項目	ADC12 A380
項目	項目名稱
項目	項目名稱
項目	項目名稱
項目	CNC 項目名稱
項目	項目名稱
MOQ	項目
公差	+/-0.01mm
項目	T / T 50mm / T;項目
項目	CNC 項目名稱
項目	項目名稱
項目	項目
項目	20-25 T / T 50mm
項目	項目
1.Name 項目OEM項目	
2.項目cnc項目	
3.項目ADC12 A380	
4.項目項目	
項目 +/- 0.01mm	
項目100項目	
7.項目OEM項目	
8.項目25-30項目	
9.項目項目	
10.項目項目	
11.項目ISO 9001	
項目	
1項目ISO項目	
項目	
項目	
項目	
項目	
項目	
7.項目項目	
項目	
項目	
項目ISO9001	
項目	
項目OEM項目	
項目OEM項目	