

### Inspection Report

**Report No.:** XYS-130723  
**Supplier :** XY-GLOBAL

**Inspection Date:** 15<sup>th</sup> Aug, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130723 Item No.XY-300985	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-300985	500PCS	5% inspection	0pcs	No failure	500pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
品番	ADC12 A380
仕様	公差 ±0.01mm
材質	ADC12
加工方法	CNC加工
公差	±0.01mm
加工精度	±0.01mm
加工時間	約50分
MOQ	100個
納期	約20-25日
梱包	10個/箱
送料	別途見積
備考	
1. OEM加工品	
2. CNC加工品	
3. ADC12 A380	
4. 公差 ±0.01mm	
5. 加工時間 約50分	
6. MOQ 100個	
7. OEM加工品	
8. 納期 約25-30日	
9. 梱包 10個/箱	
10. 送料 別途見積	
11. ISO 9001	
ISO 9001	
1. ISO 9001	
2. ISO 9001	
3. ISO 9001	
4. ISO 9001	
5. ISO 9001	
6. ISO 9001	
7. ISO 9001	
ISO 9001	
ISO 9001	
ISO 9001	
ISO 9001	
OEM加工品	

ISO 9001