

□□□□□□□□□□□□□□

Inspection Report

Report No.: XYD-130703
Supplier : XY-GLOBAL







Inspection Date: 10th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130703 Item No.XY-956400	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-956400	800PCS	5% inspection	0pcs	No failure	800pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	ชื่อ บริษัท/โรงงาน/ผู้ขาย/ผู้ส่งมอบ
รุ่น	ADC12 A380
รายละเอียด	ชื่อ รุ่น
ขนาด	ขนาด น้ำหนัก
วัสดุ	CNC อะลูมิเนียม
จำนวน	จำนวน ชิ้น
MOQ	จำนวนขั้นต่ำ
ราคา/ชิ้น	+/-0.01
ระยะเวลา	T / T 50% / T 50% / T; 30 วัน
สถานที่	CNC ผลิตใน จีน
การรับประกัน	การรับประกัน 1 ปี
บริการหลังการขาย	บริการ 24 ชั่วโมง
การชำระเงิน	20-25% T / T 50%
การขนส่ง	ทางเรือ
1. Name	บริษัท OEM
2. รายละเอียด cnc	รายละเอียด
3. รุ่น ADC12 A380	รุ่น
4. รายละเอียด น้ำหนัก	น้ำหนัก +/- 0.01mm
5. จำนวน	จำนวน 100 ชิ้น
7. ชื่อ OEM	ชื่อ OEM
8. ระยะเวลา 25-30	ระยะเวลา 25-30 วัน
9. รายละเอียด	รายละเอียด
10. รายละเอียด	รายละเอียด
11. ISO 9001	ISO 9001
ISO 9001	ISO 9001
1. ISO 10	ISO 10
รายละเอียด	รายละเอียด
รายละเอียด	รายละเอียด
รายละเอียด	รายละเอียด
ISO 9001	ISO 9001
รายละเอียด	รายละเอียด
OEM	OEM

