

**Inspection Report**

Report No.: XYAK-150416  
 Supplier : XY-GLOBAL

Inspection Date: 20<sup>th</sup> May, 2015  
 Inspector: Leo

Inspection only for: PO . XYAK-150416 Item No. XY31AL013	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL013	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	cnc加工 各種cnc加工品 各種CNC加工品 CNC加工品 CNC加工品 各種加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
形状	各種形状
用途	各種用途 各種加工品
加工	各種加工品
加工	CNC加工 各種加工品 各種加工品 各種加工品
加工	各種加工品 各種加工品 各種加工品 各種加工品 各種加工品
MOQ	1個
公差	+/-0.01mm
納期	T / T 50% 50% T / T; 各種
加工	CNC加工 cnc加工 cnc加工 cnc加工 各種加工品 各種加工品
加工	各種加工品 各種加工品 各種加工品 各種加工品 各種加工品
加工	各種加工品
加工	20-25日 T / T 50%
加工	各種加工品
1. 各種OEM cnc加工	
2. 各種cnc加工	
3. AL6061 AL6065 AL6063 AL7075 POM	
4. 各種加工品 各種加工品	
公差 +/- 0.01mm	
加工 100個	
7. OEM加工 各種加工品	
8. 各種加工品 25-30日	
9. cnc加工 各種加工品 各種加工品	
10. 各種加工品 各種加工品	
11. ISO 9001	
加工	
1. ISO加工	
加工	
各種加工品 各種加工品	
各種加工品 各種加工品	
加工	
加工	
7. 各種加工品	
加工	
各種加工品 各種加工品	
各種加工品 各種加工品	
各種加工品 ISO9001	
各種加工品 各種加工品	
各種加工品 OEM加工	

# Our sales team



□□□□□□□□□□ OEM□□□□□□ □□□□