

**Inspection Report**

Report No.: XYAN-150314  
 Supplier : XY-GLOBAL

Inspection Date: 16<sup>th</sup> Apr., 2015  
 Inspector: LEO

Inspection only for: PO . XYBA-150314      Item No. XY21ZC101	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC101	12000pcs	7% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	精密CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	図面参照
数量	数量指定あり
公差	図面参照
表面処理	図面参照
検査	図面参照
納期	図面参照
保管	図面参照
梱包	図面参照
送料	図面参照
備考	
1.	精密CNC加工
2.	図面参照
	AL6061 AL6065 AL6063 AL7075
4.	図面参照
5.	公差±0.01
6.	数量100
7.	図面参照
8.	数量25-30
9.	図面参照
10.	図面参照
11.	ISO 9001
1.10.	ISO
2.	図面参照
3.	図面参照
4.	図面参照
5.	図面参照
6.	図面参照
7.	図面参照
	ISO9001
	OEM

Safety is our serious job for our worker and engineer team

