

Inspection Report

Report No.: XYAN-150315
 Supplier : XY-GLOBAL

Inspection Date: 19th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYBA-150315 Item No. XY21ZC102	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC102	12000pcs	7% inspection	0pcs	No failure	12000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	 <p style="text-align: center;">X Y Z</p>
5. Product :	6. Inspection report:

物料	铝合金CNC加工零件CNC件
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
数量	按图
用途	工业机械零件
精度	按图
表面处理	阳极氧化 电泳 喷漆 镀锌
包装	按图
交货期	+/-0.01
起订量	500 50000
公差	按图
材料	铝合金
厚度	50 25
重量	按图
1. 铝合金CNC件	
2. 工业机械零件	
铝合金AL6061 AL6065 AL6063 AL7075	
4. 按图	
5. 公差±0.01	
6. 100	
7. 按图	
8. 25-30	
9. 按图	
10. 按图	
11. ISO 9001	
按图	
1.10. ISO	
2. 按图	
3. 按图	
4. 按图	
5. 按图	
6. 按图	
7. 按图	
按图	
按图	
按图	
按图ISO9001	
按图	
OEM	

Safety is our serious job for our worker and engineer team

