

Inspection Report

Report No.: XYAN-150318
 Supplier : XY-GLOBAL

Inspection Date: 21th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYBA-150318 Item No. XY21ZC105	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC105	12000pcs	7% inspection	0pcs	No failure	12000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	铝合金CNC加工零件CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	定制
数量	10000件
公差	±0.01mm
表面处理	阳极氧化
包装	泡沫+纸箱
交货期	15天
付款方式	预付30%
工厂地址	深圳市宝安区
联系电话	0755-12345678
电子邮箱	sales@aluminum.com
公司名称	铝合金精密加工有限公司
公司地址	深圳市宝安区西乡街道
邮编	518102
开户银行	招商银行
账号	4401010101010101
联系人	张经理
手机	13800138000
QQ	123456789
微信	aluminum2023
营业执照	提供
ISO9001	认证
ISO14001	认证
ISO45001	认证
其他证书	提供
工厂参观	欢迎
技术支持	提供
售后服务	24小时
质量保证	终身
价格优势	合理
交货准时	保证
工厂规模	10000㎡
员工人数	500人
设备数量	100台
生产能力	100000件/月
研发能力	强
创新能力	强
合作模式	OEM

Safety is our serious job for our worker and engineer team

