

**Inspection Report**

Report No.: XYKB-140510  
Supplier : XY-GLOBAL

Inspection Date: 6<sup>th</sup> Jun, 2014  
Inspector: Leo

Inspection only for: PO . XYKB-140510 Item No. XY72YM006	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM006	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :																			
																			
1. Packing	2. Product																		
																			
3. Product	4 Product																		
	<p><b>XY-GLOBAL</b> 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Inspection Report No.</td> <td>XYKB-140510</td> <td>Product Name</td> <td>XY72YM006</td> <td>Inspection Date</td> <td>June 6, 2014</td> </tr> <tr> <td>Order No.</td> <td>XYKB-140510</td> <td>Customer Name</td> <td>XY-GLOBAL</td> <td>Inspection Item</td> <td>Appearance</td> </tr> <tr> <td>Inspector</td> <td>Leo</td> <td>Inspector</td> <td>Leo</td> <td>Inspection Result</td> <td>PASS</td> </tr> </table> <p>Inspection Report No. XYKB-140510</p> <p>Product Name XY72YM006</p> <p>Customer Name XY-GLOBAL</p> <p>Inspector Leo</p> <p>Inspection Date June 6, 2014</p> <p>Inspection Item Appearance</p> <p>Inspection Result PASS</p> <p>Inspection Report No. XYKB-140510</p> <p>Product Name XY72YM006</p> <p>Customer Name XY-GLOBAL</p> <p>Inspector Leo</p> <p>Inspection Date June 6, 2014</p> <p>Inspection Item Appearance</p> <p>Inspection Result PASS</p>	Inspection Report No.	XYKB-140510	Product Name	XY72YM006	Inspection Date	June 6, 2014	Order No.	XYKB-140510	Customer Name	XY-GLOBAL	Inspection Item	Appearance	Inspector	Leo	Inspector	Leo	Inspection Result	PASS
Inspection Report No.	XYKB-140510	Product Name	XY72YM006	Inspection Date	June 6, 2014														
Order No.	XYKB-140510	Customer Name	XY-GLOBAL	Inspection Item	Appearance														
Inspector	Leo	Inspector	Leo	Inspection Result	PASS														
5. Product:	6. Dimensions report:																		

