

Inspection Report

Report No.: XYAN-150302-1
 Supplier : XY-GLOBAL

Inspection Date: 1st Apr, 2015
 Inspector: LEO

Inspection only for: PO . XYBA-150302-1 Item No. XY21ZC089	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC089	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. Inspection report:

品名	铝合金CNC加工零件CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	定制
数量	10000个
公差	±0.01mm
表面处理	阳极氧化
包装	泡沫箱+纸箱
交货期	15天
付款方式	预付30%定金
工厂地址	深圳市宝安区
联系电话	0755-12345678
联系人	张先生
电子邮箱	zhang@aluminum.com
公司网站	www.aluminum.com
认证	ISO 9001
其他	
1. 品名	铝合金CNC加工零件
2. 材料	AL6061 AL6065 AL6063 AL7075
4. 公差	±0.01mm
5. 表面处理	±0.01mm
6. 包装	100个
7. 交货期	15天
8. 付款方式	25-30%
9. 工厂地址	深圳市宝安区
10. 联系电话	
11. 认证	ISO 9001
其他	
1.10. 品名	ISO 9001
2. 材料	
3. 公差	
4. 包装	
5. 交货期	
6. 付款方式	
7. 工厂地址	
其他	
品名	铝合金CNC加工零件
材料	AL6061 AL6065 AL6063 AL7075
公差	±0.01mm
表面处理	阳极氧化
包装	泡沫箱+纸箱
交货期	15天
付款方式	预付30%定金
工厂地址	深圳市宝安区
联系电话	0755-12345678
联系人	张先生
电子邮箱	zhang@aluminum.com
公司网站	www.aluminum.com
认证	ISO 9001
其他	
品名	OEM定制

Safety is our serious job for our worker and engineer team

