

**Inspection Report**

Report No.: XYN-140604  
 Supplier : XY-GLOBAL

Inspection Date: 2<sup>nd</sup> July, 2014  
 Inspector: Leo

Inspection only for: PO . XYN-140604 Item No.100583	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
100583	10000PCS	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b>
No failure.
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product::
	
5. Product:	6. Report:

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
公差	&NBSP; ±0.01
表面処理	
加工機	CNC加工機
加工時間	gague
重量	
寸法	+/-0.01
公差	T / T 50 50 T / T
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name CNC加工品	
2.Process	
AL6061 AL6065 AL6063 AL7075	
4.	
5.Tolerance ±0.01	
6.100	
7.Specification serice	
8.25-30	
9.CNC accessoried	
10.Austrial	
11.&NBSP; ISO 9001	
1 ISO	
2	
3 kinds available	
4	
5	
6	
7	
&NBSP;	
ISO9001	