

Inspection Report

Report No.: XYSL-150605
Supplier : XY-GLOBAL

Inspection Date: 10th July, 2015
Inspector: Leo

Inspection only for: PO . XYSL-150605 Item No. XY31XL003	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL003	42000PCS	1% inspection	0pcs	No failure	42000pcs







Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	
表面処理	
検査	
納期	
備考	
1. 公差	+/-0.01
2. 検査	50%
3. 納期	
4. 備考	
5. 公差	±0.01
6. 検査	100%
7. 納期	
8. 備考	25-30
9. 公差	
10. 検査	
11. 納期	ISO 9001
品名	
1.10. 公差	ISO
2. 検査	
3. 納期	
4. 備考	
5. 公差	
6. 検査	
7. 納期	
品名	
公差	
検査	
納期	ISO9001
備考	
OEM	

Safety is our serious job for our worker and engineer team

