XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYSL-140614
Supplier : XY-GLOBAL

Inspection Date: 19th Jul, 2014
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYSL-140614 Item No. XY11WD038	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD038	18000PCS	5% inspection	0pcs	No failure	18000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:



6. The test report

□□□□	□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□OEM□□□□□□□□
□□	□□□ADC12□A380□
□□	□□□□□□□
□□□□	□□□□□□□□□□□□□□□□□□□□□□
□□	□□□□□□□□□
□□□□	□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□ □□□
□□□□	□□□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□
□□□□□	□□□□□□
□□/□□	+/-0.01□□
□□	□□□□50□□□□□□□□□□□□□50□□□□
□□□□	□□□
□□	□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□
□□	□□□□
□□	□□□□□50□□□□□25□□□
□□□□	□□□□□□□□□□□□□
1.□□□ □□□□□□□□□□	
2.□□□ □□□□□□□□□□□□□□□□□□	
3.□□□□□□ADC12□A380□	
4.□□□□□□□□□□□□□□□□□□ □□□□	
5.□□□□□□±0.01□□	
6.□□□□□100□□	
7.□□□□□□□□□□□□□□□□□□□□□□□	
8.□□□□□25-30□□	
9.□□□□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□□	
10.□□□□□□□□□□□□□□□□□□□□	
11.□□□□□□□□ISO 9001	
□□□□□	
1.10□□□□□ISO□□	
2.□□□□□□□□□□□□□□□□	
3.□□□□□□□□□□□□□□□□	
4.□□□□□□□□□□□□□	
5.□□□□□	
6.□□□□□□	
7.□□□□□□□□□□□□□	
□□□□□	
□□□□□□□□□□□□□□□□□□	
□□□□□□□□□□□□	
□□□□□□□ISO9001	
□□□□□□□□□□□□□□□□	
□□OEM□□□□□□□□	