

Inspection Report

Report No.: XYAK-150402
 Supplier : XY-GLOBAL

Inspection Date: 8th May, 2015
 Inspector: Leo

Inspection only for: PO . XYAK-150402 Item No. XY31AL001	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL001	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

材料	铝合金CNC加工零件CNC
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
精度	±0.05mm
公差	±0.02mm
表面处理	阳极氧化
最小壁厚	0.5mm
最小孔径	0.3mm
最大长度	1000mm
最大重量	50kg
交货周期	3-5天
付款方式	电汇
售后服务	提供技术支持
认证	ISO 9001
其他	
1. 材料	铝合金CNC
2. 规格	AL6061 AL6065 AL6063 AL7075
3. 精度	±0.05mm
4. 公差	±0.02mm
5. 表面处理	阳极氧化
6. 最小壁厚	0.5mm
7. 最小孔径	0.3mm
8. 最大长度	1000mm
9. 最大重量	50kg
10. 交货周期	3-5天
11. 付款方式	电汇
12. 售后服务	提供技术支持
13. 认证	ISO 9001
14. 其他	
15. 1.10 材料	铝合金CNC
16. 2. 规格	AL6061 AL6065 AL6063 AL7075
17. 3. 精度	±0.05mm
18. 4. 公差	±0.02mm
19. 5. 表面处理	阳极氧化
20. 6. 最小壁厚	0.5mm
21. 7. 最小孔径	0.3mm
22. 8. 最大长度	1000mm
23. 9. 最大重量	50kg
24. 10. 交货周期	3-5天
25. 11. 付款方式	电汇
26. 12. 售后服务	提供技术支持
27. 13. 认证	ISO 9001
28. 14. 其他	
29. 15. OEM	提供技术支持

Safety is our serious job for our worker and engineer team

