

Inspection Report

Report No.: XYL-150801
 Supplier : XY-GLOBAL

Inspection Date:14th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150801 Item No. XY11XL044	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL044	14000PCS	1% inspection	0pcs	No failure	14000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:



High qualified surface treatment can make your parts perfect !!!

