

**Inspection Report**

Report No.: XYL-150806  
Supplier : XY-GLOBAL

Inspection Date: 17<sup>th</sup> Sep, 2015  
Inspector: Leo

Inspection only for: PO . XYL-150806 Item No. XY11XL049	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL049	17000PCS	1% inspection	0pcs	No failure	17000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:



High qualified surface treatment can make your parts perfect !!!

