

**Inspection Report**







Report No.: XYSL-150722  
 Supplier : XY-GLOBAL

Inspection Date: 25<sup>th</sup> Aug, 2015  
 Inspector: Leo

Inspection only for: PO . XYSL-150722 Item No. XY31XL042	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL042	13000PCS	1% inspection	0pcs	No failure	13000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AI7075 SUS304 SUS303 SUS316
仕様	
公差	±0.05
表面処理	研磨
加工方法	CNC加工
検査方法	gauge
MOQ	100
公差	+/-0.01
納期	T / T 50% 50%
加工方法	CNC加工
品質保証	品質保証書発行
納期	20-25 T / T 50%
検査方法	検査
1. Name OEM	
2. CNC	
3. AL6061 AL6065 AL6063 AI7075 POM	
4. 公差	
5. Tolerance +/-0.01	
6. 100	
7. Specification OEM	
8. 25-30	
9. CNC accessoried	
10. 公差	
11. ISO 9001	
品質保証	
1. ISO	
2. 品質保証	
3. kinds surface available	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
品質保証	
品質保証	
品質保証 ISO9001	
品質保証	
品質保証 OEM	

Safety is our serious job for our worker and engineer team

