

Inspection Report

Report No.: XYDS-140627
 Supplier : XY-GLOBAL

Inspection Date: 25th July, 2014
 Inspector: Leo

Inspection only for: PO . XYDS-140627 Item No.7089200	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
7089200	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

品名	汎用CNC加工品汎用CNC
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	汎用加工品
用途	汎用加工品
公差	汎用加工品
表面処理	汎用加工品
検査	汎用加工品
納期	汎用加工品
価格	汎用加工品
単位	個
最小ロット	50個
最大ロット	50個
公差	+/-0.01mm
表面処理	汎用加工品
検査	汎用加工品
納期	汎用加工品
価格	汎用加工品
単位	個
最小ロット	50個
最大ロット	25個
公差	汎用加工品
1.汎用加工品CNC	
2.汎用加工品	
汎用加工品AL6061 AL6065 AL6063 AL7075	
4.汎用加工品	
5.公差±0.01mm	
6.最小ロット100個	
7.汎用加工品	
8.公差25-30mm	
9.汎用加工品	
10.汎用加工品	
11.汎用加工品ISO 9001	
汎用加工品	
1.10汎用加工品ISO	
2.汎用加工品	
3.汎用加工品	
4.汎用加工品	
5.汎用加工品	
6.汎用加工品	
7.汎用加工品	
汎用加工品	
汎用加工品	
汎用加工品	
汎用加工品ISO9001	
汎用加工品	
汎用加工品	
汎用OEM加工品	