

Inspection Report

Report No.: XYL-150805
Supplier : XY-GLOBAL

Inspection Date: 17th Sep, 2015
Inspector: Leo

Inspection only for: PO . XYL-150805 Item No. XY11XL048	<u>Inspection Result:</u> PASS
------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL048	17000PCS	1% inspection	0pcs	No failure	17000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :													
													
1. Packing	2. Product												
													
3. Product	4 Product												
	 <p>检查报告</p> <p>品名: XY11XL048 日期: 17 09 2015 检验员: Leo</p> <table border="1"> <thead> <tr> <th>品名</th> <th>规格</th> <th>数量</th> <th>检验日期</th> <th>检验员</th> <th>检验结果</th> </tr> </thead> <tbody> <tr> <td>XY11XL048</td> <td>17000PCS</td> <td>17000</td> <td>17/09/2015</td> <td>Leo</td> <td>PASS</td> </tr> </tbody> </table>	品名	规格	数量	检验日期	检验员	检验结果	XY11XL048	17000PCS	17000	17/09/2015	Leo	PASS
品名	规格	数量	检验日期	检验员	检验结果								
XY11XL048	17000PCS	17000	17/09/2015	Leo	PASS								
5. Product:	6. Report:												



High qualified surface treatment can make your parts perfect !!!

