



Inspection Report

Report No.: XYJ-131015
 Supplier : XY-GLOBAL

Inspection Date:9th Nov-, 2013
 Inspector:LEO

Inspection only for: PO . XYJ-131015 Item No.XY-CT-D-060	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-060	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing




2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	品名: 各種 CNC 加工品
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	仕様: 各種
数量	数量: 各種
公差	公差: 各種
加工方法	CNC 加工
表面処理	表面処理: gague
単位	単位: 個
公差	+/-0.01
公差	T / T 50 50 T / T
公差	公差: 各種
公差	公差: 各種
公差	T / T 50 20-25 NBSP
公差	公差: 各種
1.Name 各種 CNC 加工品	
2.Process 各種 CNC 加工	
各種 AL6061 AL6065 AL6063 AL7075	
4. 各種 CNC 加工品	
5.Tolerance 各種 ±0.01	
6. 各種 100	
7.Specification 各種 serice	
8. 各種 25-30	
9. 各種 accessoried	
10. 各種 Austrial	
11 &NBSP; 各種 ISO 9001	
各種 各種	
1. 10 各種 ISO	
2. 各種	
3. 各種 kinds available	
4. 各種	
5. 各種	
6. 各種	
7. 各種	
各種 各種	
各種 &NBSP; 各種	
各種 各種	
各種 ISO9001	
各種 各種	
各種 各種	