

**Inspection Report**

Report No.: XYL-150814  
 Supplier : XY-GLOBAL

Inspection Date: 23<sup>th</sup> Sep, 2015  
 Inspector: Leo

Inspection only for: PO . XYL-150814 Item No. XY11XL057	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL057	18000PCS	1% inspection	0pcs	No failure	18000pcs

**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:





High qualified surface treatment can make your parts perfect !!!

