

Inspection Report

Report No.: XYSS-131010
 Supplier : XY-GLOBAL

Inspection Date: 25th Nov., 2013
 Inspector: LEO

Inspection only for: PO . XYSS-131010 Item No. Cylinder_FirstAid	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Cylinder_FirstAid	6PCS	100% inspection	0pcs	No failure	6pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	铝合金 CNC 加工零件
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	见附图
数量	10000 件
公差	±0.01
表面处理	阳极氧化
检验标准	ISO 9001
交货期	30 天
付款方式	预付 30% 定金
包装方式	纸箱包装
备注	
1.Name	铝合金 CNC 加工零件
2.Process	CNC 加工
3.Material	AL6061 AL6065 AL6063 AL7075
4.Tolerance	±0.01
5.Quantity	10000
6.Specification	ISO 9001
7.Surface Treatment	阳极氧化
8.Delivery Time	30 天
9.Payment Terms	预付 30% 定金
10.Packaging	纸箱包装
11.ISO 9001	符合 ISO 9001 标准
其他要求	
1. 符合 ISO 9001 标准	
2. 表面处理	
3. 交货期	30 天
4. 付款方式	预付 30% 定金
5. 包装方式	纸箱包装
6. 备注	
7. 其他要求	
其他要求	
符合 ISO 9001 标准	
表面处理	
交货期	30 天
付款方式	预付 30% 定金
包装方式	纸箱包装
备注	