

Inspection Report

Report No.: XYF-130802
Supplier : XY-GLOBAL

Inspection Date:1th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYK-130802 Item No.300-20017	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
300-20017	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

