

**Inspection Report**

Report No.: XYSL-140613  
Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Jul, 2014  
Inspector: Leo

Inspection only for: PO : XYSL-140613 Item No. XY11WD037	<b>Inspection Result:</b> <b>PASS</b>
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD037	20000PCS	5% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing 2. Product



3. Product 4 Product

--	--

5. Product: 6. The test report

