

Inspection Report

Report No.: XYL-150720
 Supplier : XY-GLOBAL

Inspection Date: 5th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150720 Item No. XY11LM020	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM020	11000PCS	1% inspection	0pcs	No failure	11000pcs

Appearance Inspection :
 No failure.

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :



5. Product:	6. Report:
-------------	------------

The report image shows a detailed inspection table with columns for 'Spec', 'Unit', 'Value', 'Tolerance', and 'Status'. The table contains multiple rows of data, all of which appear to be within tolerance and marked as 'OK'.

Safety is our serious job for our worker and engineer team

