

Inspection Report

Report No.: XYSL-150609
 Supplier : XY-GLOBAL

Inspection Date: 15th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150609 Item No. XY31XL007	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL007	10000PCS	1% inspection	0pcs	No failure	10000pcs





Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p>	<p>2. Product</p>
	
<p>3. Product</p>	<p>4 Product</p>
	
<p>5. Product:</p>	<p>6. report</p>

Safety is our serious job for our worker and engineer team

