

**Inspection Report**

**Report No.:** XYD-140508  
**Supplier :** XY-GLOBAL

**Inspection Date:** 6<sup>th</sup> Jun, 2014  
**Inspector:** Alex

Inspection only for: PO . XYD-140508 Item No.XY-1415249	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1415249	<b>10000PCS</b>	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b>
No failure.
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	ADC12 A380 OEM
品番	ADC12 A380
メーカー	
仕様	
単位	
材質	
公差	+/-0.01
表面処理	T / T 50
検査	
包装	
納期	
備考	
1.Name	ADC12 A380
2.Process	
3.品番	ADC12 A380
4.公差	+/-0.01
5.Tolerance	+/-0.01
6.単位	100
7.Specification	serice
8.検査	25-30
9.包装	accessoried
10.備考	Austrial
11.&NBSP;	ISO 9001
品名	
1.品番	ISO
2.単位	
3.仕様	kindls available
4.公差	
5.単位	
6.単位	
7.単位	
品名	
品番	&NBSP;
単位	
仕様	ISO9001
公差	
備考	OEM