

Inspection Report


Report No.: XYSK-140522
Supplier : XY-GLOBAL

Inspection Date: 24th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYSK-140522 Item No. XY11WD021	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD021	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report

品名	品名 品名品名品名品名品名品名 品名品名OEM品名品名品名品名 品名
品名	品名 ADC12品名A380品名
品名	品名 品名品名
品名	品名 品名品名品名品名品名品名品名 品名品名
品名	品名 品名品名品名品名
品名	CNC 品名品名品名品名品名品名品名品名品名品名品名品名品名
品名	品名 品名品名品名gague品名品名品名品名品名品名品名品名品名品名品名品名品名 品名
MOQ	品名
品名/品名	+/-0.01品名
品名	T / T 50品名品名品名50品名T / T品名;品名品名
品名	CNC 品名品名品名品名品名品名品名品名品名品名品名品名品名
品名	品名 品名品名品名品名品名品名品名品名品名品名品名品名
品名	品名 品名
品名	20-25品名 T / T 50品名品名品名
品名	品名 品名品名
1.Name品名品名OEM品名品名品名	
2.Process品名品名品名品名品名	
3.品名品名品名ADC12品名A380品名	
4.品名品名品名品名品名品名品名品名品名 品名品名	
5.Tolerance品名+/-0.01品名	
6.Quality品名品名100品名品名	
7.Specification品名OEM serice品名品名品名品名品名	
8.品名品名品名品名25-30品名品名品名品名	
9.品名品名品名品名品名品名 品名accessoried品名品名品名品名	
10.品名品名品名品名品名Austrial品名品名品名	
11.品名品名ISO 9001	
品名品名	
1. 10品名品名品名ISO品名	
2.品名品名品名	
3.品名品名品名品名kindls品名available	
4.品名品名品名品名品名	
5.品名品名品名	
6.品名品名品名	
7.品名品名品名品名品名品名	
品名品名	
品名品名品名品名品名品名品名 品名	
品名品名品名品名品名品名	
品名品名品名品名品名ISO9001	
品名品名品名品名品名品名品名品名 品名	
品名品名品名OEM品名品名	