

Inspection Report

Report No.: XYSL-150603
 Supplier : XY-GLOBAL

Inspection Date: 2th July, 2015
 Inspector: Leo

| | |
|--|--|
| Inspection only for: PO . XYSL-150603 Item No. XY31XL002 | <u>Inspection Result:</u> PASS |
|--|--|





| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31XL002 | 22000PCS | 1% inspection | 0pcs | No failure | 22000pcs |

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

| | |
|---|---|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. report |

Safety is our serious job for our worker and engineer team

