

**Inspection Report**

Report No.: XYL-150723  
 Supplier : XY-GLOBAL

Inspection Date: 8<sup>th</sup> Sep, 2015  
 Inspector: Leo

Inspection only for: PO . XYL-150723 Item No. XY11LM023	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM023	16000PCS	1% inspection	0pcs	No failure	16000pcs







**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:



Safety is our serious job for our worker and engineer team

