

**Inspection Report**

**Report No.:** XYI-140314  
**Supplier :** XY-GLOBAL

**Inspection Date:** 10<sup>th</sup> Apr, 2014  
**Inspector:** Leo

Inspection only for: PO . XYI-140314 Item No.141030	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
141030	10000PCS	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	ステンレス鋼製精密加工品OEM加工品
品番	ADC12 A380
材質	ステンレス鋼
仕様	精密加工品
加工方法	CNC加工
公差	±0.01mm
表面処理	研磨
検査方法	目視検査
納入仕様	T / T 50% 前払い
納期	約2-3週間
梱包	個包装
備考	ISO 9001 認証工場
1.Name	ステンレス鋼製精密加工品
2.Process	CNC加工
3.材料	ADC12 A380
4.公差	±0.01mm
5.Tolerance	±0.01mm
6.表面処理	研磨
7.Specification	serice
8.検査方法	目視検査
9.付属品	accessoried
10.納入仕様	Austrial
11.&NBSP;	ISO 9001
品名	
1.品番	ISO
2.材質	
3.仕様	kindls available
4.加工方法	
5.公差	
6.表面処理	
7.検査方法	
品名	
品番	ISO9001
材質	
仕様	
加工方法	OEM