

**Inspection Report**

Report No.: XYL-150815  
 Supplier : XY-GLOBAL

Inspection Date: 23<sup>th</sup> Sep, 2015  
 Inspector: Leo

Inspection only for: PO . XYL-150815 Item No. XY11XL058	<b>Inspection Result:</b> PASS
------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL058	18000PCS	1% inspection	0pcs	No failure	18000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:



High qualified surface treatment can make your parts perfect !!!

