

Inspection Report

Report No.: XYN-140622
Supplier : XY-GLOBAL

Inspection Date: 17th July, 2014
Inspector: Leo

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYN-140622 Item No.302698 | <u>Inspection Result:</u> PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| 302698 | 15000PCS | 1% inspection | 0pcs | No failure | 15000pcs |

| |
|--|
| Appearance Inspection : |
| No failure. |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

| | |
|---|--|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. Report: |

