

Inspection Report







Report No.: XYSL-150619
 Supplier : XY-GLOBAL

Inspection Date: 25th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150619 Item No. XY31XL017	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL017	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

Safety is our serious job for our worker and engineer team

