

Inspection Report

Report No.: XYFD-130804
Supplier : XY-GLOBAL

Inspection Date: 3th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYFD-130804 Item No.400-10-071	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

00	00 00000000 cnc 0000000000 0000000000 CNC 00000000 CNC 00 000000000000000000
00	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
0000	00000000
0000	00000000 0000000000000000
00	000000000000
0000	0000000000000000 0000000000000000 CNC 0000
0000	0000000000000000 00000000000000000000 00000000000000000000 0000
MOQ	00
00/00	+/-0.01
00	T / T 50 0000 50 T / T 000; 0000
0000	CNC 0000 CNC 0000 cnc 0000 cnc 0000 0000000000000000000000 00
00	000000000000000000 0000000000 cnc 0000 0000
00	0000
00	20-25 T / T 50 0000
0000	cnc 0000
1.Name 0000 OEM cnc 0000	
2.00000000 cnc 00	
3.0000 AL6061 AL6065 AL6063 AL7075 POM	
4.00000000000000000000 0000	
0000 +/- 0.01mm	
0000 100 0000	
7.0000 OEM 00000000000000	
8.0000000000 25-30 00	
9.0000 cnc 0000000000 00000000000000	
10.000000000000000000	
11.0000 ISO 9001	
0000 00	
1 10 ISO 0000	
00000000	
0000000000000000	
00000000000000	
000000	
0000	
7.000000000000	
0000-00	
00000000000000	
00000000000000	
00000000 ISO9001	
0000000000000000	
00000000 OEM 0000	
Oem 0000 china 0 oem 00000000000000000000	