

**Inspection Report**







Report No.: XYL-150813  
Supplier : XY-GLOBAL

Inspection Date: 20<sup>th</sup> Sep, 2015  
Inspector: Leo

Inspection only for: PO : XYL-150813 Item No. XY11LM043	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM043	16000PCS	1% inspection	0pcs	No failure	16000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

**検査報告**

検査日: 2015/09/20  
検査所: XY-GLOBAL  
検査員: Leo

項目	規格	実測	判定	備考
外径	16.000	16.000	OK	
内径	12.000	12.000	OK	
長さ	40.000	40.000	OK	
穴径	4.000	4.000	OK	
穴深	10.000	10.000	OK	
穴位置	10.000	10.000	OK	
穴位置	30.000	30.000	OK	
穴位置	40.000	40.000	OK	
穴位置	50.000	50.000	OK	
穴位置	60.000	60.000	OK	
穴位置	70.000	70.000	OK	
穴位置	80.000	80.000	OK	
穴位置	90.000	90.000	OK	
穴位置	100.000	100.000	OK	
穴位置	110.000	110.000	OK	
穴位置	120.000	120.000	OK	
穴位置	130.000	130.000	OK	
穴位置	140.000	140.000	OK	
穴位置	150.000	150.000	OK	
穴位置	160.000	160.000	OK	
穴位置	170.000	170.000	OK	
穴位置	180.000	180.000	OK	
穴位置	190.000	190.000	OK	
穴位置	200.000	200.000	OK	
穴位置	210.000	210.000	OK	
穴位置	220.000	220.000	OK	
穴位置	230.000	230.000	OK	
穴位置	240.000	240.000	OK	
穴位置	250.000	250.000	OK	
穴位置	260.000	260.000	OK	
穴位置	270.000	270.000	OK	
穴位置	280.000	280.000	OK	
穴位置	290.000	290.000	OK	
穴位置	300.000	300.000	OK	
穴位置	310.000	310.000	OK	
穴位置	320.000	320.000	OK	
穴位置	330.000	330.000	OK	
穴位置	340.000	340.000	OK	
穴位置	350.000	350.000	OK	
穴位置	360.000	360.000	OK	
穴位置	370.000	370.000	OK	
穴位置	380.000	380.000	OK	
穴位置	390.000	390.000	OK	
穴位置	400.000	400.000	OK	
穴位置	410.000	410.000	OK	
穴位置	420.000	420.000	OK	
穴位置	430.000	430.000	OK	
穴位置	440.000	440.000	OK	
穴位置	450.000	450.000	OK	
穴位置	460.000	460.000	OK	
穴位置	470.000	470.000	OK	
穴位置	480.000	480.000	OK	
穴位置	490.000	490.000	OK	
穴位置	500.000	500.000	OK	
穴位置	510.000	510.000	OK	
穴位置	520.000	520.000	OK	
穴位置	530.000	530.000	OK	
穴位置	540.000	540.000	OK	
穴位置	550.000	550.000	OK	
穴位置	560.000	560.000	OK	
穴位置	570.000	570.000	OK	
穴位置	580.000	580.000	OK	
穴位置	590.000	590.000	OK	
穴位置	600.000	600.000	OK	
穴位置	610.000	610.000	OK	
穴位置	620.000	620.000	OK	
穴位置	630.000	630.000	OK	
穴位置	640.000	640.000	OK	
穴位置	650.000	650.000	OK	
穴位置	660.000	660.000	OK	
穴位置	670.000	670.000	OK	
穴位置	680.000	680.000	OK	
穴位置	690.000	690.000	OK	
穴位置	700.000	700.000	OK	
穴位置	710.000	710.000	OK	
穴位置	720.000	720.000	OK	
穴位置	730.000	730.000	OK	
穴位置	740.000	740.000	OK	
穴位置	750.000	750.000	OK	
穴位置	760.000	760.000	OK	
穴位置	770.000	770.000	OK	
穴位置	780.000	780.000	OK	
穴位置	790.000	790.000	OK	
穴位置	800.000	800.000	OK	
穴位置	810.000	810.000	OK	
穴位置	820.000	820.000	OK	
穴位置	830.000	830.000	OK	
穴位置	840.000	840.000	OK	
穴位置	850.000	850.000	OK	
穴位置	860.000	860.000	OK	
穴位置	870.000	870.000	OK	
穴位置	880.000	880.000	OK	
穴位置	890.000	890.000	OK	
穴位置	900.000	900.000	OK	
穴位置	910.000	910.000	OK	
穴位置	920.000	920.000	OK	
穴位置	930.000	930.000	OK	
穴位置	940.000	940.000	OK	
穴位置	950.000	950.000	OK	
穴位置	960.000	960.000	OK	
穴位置	970.000	970.000	OK	
穴位置	980.000	980.000	OK	
穴位置	990.000	990.000	OK	
穴位置	1000.000	1000.000	OK	



Safety is our serious job for our worker and engineer team

