

**Inspection Report**

Report No.: XYLA-150404  
 Supplier : XY-GLOBAL

Inspection Date: 11<sup>th</sup> May, 2015  
 Inspector: Leo

Inspection only for: PO . XYLA-150404 Item No. XY31PC014	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC014	15000PCS	1% inspection	0pcs	No failure	15000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report





High qualified surface treatment can make your parts perfect !!!

