

Inspection Report

Report No.: XYL-150301
 Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150301 Item No. XY31PC001	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC001	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	
面粗	
バリ	
検査	
納期	
送料	
備考	
1.	CNC加工
2.	
3.	AL6061 AL6065 AL6063 AL7075
4.	
5.	±0.01mm
6.	100mm
7.	
8.	25-30mm
9.	
10.	
11.	ISO 9001
1.10	ISO
2.	
3.	
4.	
5.	
6.	
7.	
	ISO9001
	OEM

Safety is our serious job for our worker and engineer team

