

**Inspection Report**

Report No.: XYG-150318  
 Supplier : XY-GLOBAL

Inspection Date: 28<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYG-150318 Item No. XY11WD058	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD058	18000PCS	1% inspection	Opcs	No failure	18000pcs


**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. Report:</p>



# Customer's Feedback



Dear Ivy,

I am very satisfied with Scott and I feel it's a great cooperation between XY Global and GST. I hope we can continue in such a perfect way in future.

Yours sincerely

Nicole Holtschke  
Einkauf / Purchasing

**01**  
OPTION



Hi Ivy,

Thanks for your email.

Jack is providing me with excellent service and I have been very happy with what you produce.

We hope to work long term with you also but my business partner has asked for other quotes before we make the next batch of products.

Still waiting to get them all back. Thank you!

Regards,  
Scott James | Director

**02**  
OPTION



Dear Ivy,

I am happy and no problem dealing with Scott, hope will keep good cooperation and relationship with your esteemed company.

Thanks  
Regards  
Siao

**03**  
OPTION



Hello Ivy,

Naky has always been very responsive and met our requirements well.

I have no problem doing business with XY-Global.

Kind Regards  
Keith



**04**  
OPTION



Dear Ivy,

thank you for reaching out.  
we are happy to work with nancy and looking forward to a long term cooperation.

best,

\_\_\_\_\_  
Sigmar Berg

**05**  
OPTION