

Inspection Report

Report No.: XYN-140529
 Supplier : XY-GLOBAL

Inspection Date: 25th Jun, 2014
 Inspector: Ken

Inspection only for: PO . XYN-140529 Item No.201790	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
201790	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	品名 品名 品名 品名 品名 CNC 品名 CNC 品名 CNC 品名 CNC
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
仕様	
数量	
単位	
加工方法	CNC
加工条件	gague
公差	
寸法	+/-0.01
表面処理	T / T 50 T / T 50 T / T
検査方法	
検査項目	
検査結果	T / T 50 20-25 NBSP
検査場所	
1.Name 品名 cnc	
2.Process	
品名 AL6061 AL6065 AL6063 AL7075	
4.品名	
5.Tolerance ±0.01	
6.品名 100	
7.Specification serice	
8.品名 25-30	
9.品名 accessored	
10.品名 Austrial	
11&NBSP; ISO 9001	
品名	
1.品名 ISO	
2.品名	
3.品名 kinds available	
4.品名	
5.品名	
6.品名	
7.品名	
品名	
品名 &NBSP; 品名	
品名	
品名 ISO9001	
品名	
品名	