

Inspection Report

Report No.: XYSS-130904
 Supplier : XY-GLOBAL

Inspection Date: 11th Oct-, 2013
 Inspector: LEO

Inspection only for: PO . XYSS-130904 Item No. Samples of aluminum alloy part	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Samples of aluminum alloy part	6PCS	100% inspection	0	No failure	6pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Packing
3. Product:	4. Product:
5. Product :	6. Product:

