

Inspection Report

Report No.: XYL-150726
 Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150726 Item No. XY11LM026	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM026	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. Report:</p>

High qualified surface treatment can make your parts perfect !!!

