

Inspection Report

Report No.: XYL-150719
 Supplier : XY-GLOBAL

Inspection Date: 3th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150719 Item No. XY11LM019	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM019	11000PCS	1% inspection	Opcs	No failure	11000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

Safety is our serious job for our worker and engineer team

