

**Inspection Report**

Report No.: XYAK-150415  
 Supplier : XY-GLOBAL

Inspection Date: 20<sup>th</sup> May, 2015  
 Inspector: Leo

Inspection only for: PO . XYAK-150415 Item No. XY31AL012	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31AL012	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	汎用CNC加工品汎用CNC
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	汎用仕様
公差	汎用公差
表面	汎用表面
検査	汎用検査
梱包	汎用梱包
納期	汎用納期
備考	
単位	個
公差	+/-0.01
表面	50μm
検査	汎用検査
単位	個
公差	50μm 25μm
表面	汎用表面
1.汎用CNC	
2.汎用	
汎用AL6061 AL6065 AL6063 AL7075	
4.汎用	
5.公差±0.01	
6.表面100μm	
7.汎用	
8.公差25-30	
9.汎用	
10.汎用	
11汎用ISO 9001	
汎用	
1.10汎用ISO	
2.汎用	
3.汎用	
4.汎用	
5.汎用	
6.汎用	
7.汎用	
汎用	
汎用	
汎用	
汎用ISO9001	
汎用	
汎用OEM	

Safety is our serious job for our worker and engineer team

