

Inspection Report

Report No.: XYD-140515
Supplier : XY-GLOBAL

Inspection Date: 11th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYD-140515 Item No.XY-143241	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-143241	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
材質	
公差	+/-0.01
表面処理	T / T 50
検査方法	
納入期	
備考	
1.Name	ADC12 A380
2.Process	
3.品番	ADC12 A380
4.公差	+/-0.01
5.Tolerance	+/-0.01
6.表面処理	T / T 50
7.Specification	
8.検査方法	
9.付属品	accessories
10.納入期	
11.&NBSP;	ISO 9001
備考	
1.品番	ISO
2.仕様	
3.種類	kindls available
4.数量	
5.単位	
6.材質	
7.公差	
備考	
1.&NBSP;	ISO 9001
2.品番	
3.公差	
4.表面処理	
5.検査方法	
6.納入期	
7.&NBSP;	OEM