

Inspection Report

Report No.: XYK-140530
Supplier : XY-GLOBAL

Inspection Date: 26th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140530 Item No.XY-144320	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-144320	80000PCS	1% inspection	0pcs	No failure	80000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕入先	
仕様	
公差	+/-0.01
検査	T / T 50
材料	50 T / T
数量	
納期	20-25 T / T 50
備考	
1.Name	
2.Process	
ADC12 A380	
4.公差	
5.Tolerance ±0.01	
6.検査	
7.Specification	
8.納期	
9.accessoried	
10.Austrial	
11.&NBSP; ISO 9001	
1 ISO	
2	
3 kinds available	
4	
5	
6	
7	
&NBSP;	
ISO9001	
OEM	